

FILE COPY ORIGINAL

BellSouth D.C., Inc.
Suite 900
1133 21st Street NW
Washington, DC 20036-3351

steve.long@bellsouth.com

Steven D. Long
Assistant Manager
Federal Regulatory

202 463 4107
Fax 202 463 4631

August 22, 2005

RECEIVED

AUG 22 2005

Ms. Marlene H. Dortch
Secretary
Federal Communications Commission
445 Twelfth Street, S.W.
Washington, DC 20554

Federal Communications Commission
Office of Secretary

Re: Notices of Network Change Under Rule 51.329(a) CC Docket No. 96-98

Dear Ms. Dortch:

BellSouth Telecommunications, Inc. ("BellSouth") hereby submits the attached original and two copies of its Notices of Network Change Under Rule 51.329(a) in accordance with the requirements set forth in the Commission's Second Report and Order and Memorandum Opinion and Order released August 8, 1996, in CC Docket No. 96-98. A description of the network change is provided below:

Number	Type of Change Planned	Location of Change
20050125 Revision 20040337	Replacing Copper with Fiber	Miami, FL
20050126 Revision 20040336	Replacing Copper with Fiber	Miami Shores, FL
20050128	Replacing Copper with Fiber	Richmond, KY

As required, one paper copy and one diskette copy is being submitted to the Chief of the Common Carrier Bureau's Network Services Division. A copy of the notice is also available at:

<http://www.interconnection.bellsouth.com/notifications/network/index.html>

Should you have any questions regarding this submission, please contact me at (202) 463-4107.

Sincerely,

Attachments

No. of Copies rec'd 0 + 2
List A B C D E

cc: Julie Veach (with diskette)

Carmell Weathers (with diskette)

**Revision to Notice of Network Change – Miami, Florida
Replacing Copper Facilities with Fiber and Digital Loop Carrier Systems
Carrier**

BellSouth Telecommunications, Inc.
675 West Peachtree Street NE
Atlanta, Georgia 30375

Attachment to the revised notification contains addresses affected by the removal of copper facilities.

Date Changes are to Occur: First Quarter 2006

Notice of Network Change:

Notice of Network Change ND20040337, originally posted on January 7, 2005, regarding Replacing Copper Facilities with Fiber and Digital Loop Carrier Systems in Miami, FL.

Issue 2: Reason for Revision:

Due to the complexity of the work required and due to the current workload assigned to construction resources, the completion of this work has been rescheduled for the first quarter of 2006.

For further information please review the revised Notice of Network Change.

**Revised - Notice of Network Change – Miami, Florida
Replacing Copper Facilities with Fiber and Digital Loop Carrier Systems**

Carrier

BellSouth Telecommunications, Inc.
675 West Peachtree Street NE
Atlanta, Georgia 30375

Attachment contains addresses affected by the removal of copper facilities.

Date Changes are to Occur: First Quarter of 2006

Location of Changes: OFFICE BUILDINGS AT 10050 NE 2ND AV AND 9990 NE 2ND AV.

Description of Change Planned: Copper Facilities will be replaced with Fiber Optic cable and Digital Loop Carrier systems.

Description of Reasonably Foreseeable Impact of the Planned Change: After this work is completed, metallic facilities from the Central Office to the affected area will no longer be available. Unbundled loops that are defined as compatible with Digital Loop Carrier (DLC), e.g., those defined to transport POTS-grade service, will be transferred to the new DLC system. Competitive carriers employing unbundled loops that are defined to require metallic facilities, e.g., Digital Subscriber Line (DSL) or line sharing circuits, will be notified individually. This notification is intended to allow the affected carrier to convert the circuit to one compatible with DLC.

It should be noted that if a competitive carrier obtains an unbundled loop that has been defined to transport POTS-grade service, but then utilizes the POTS-grade loop to provide DSL service, BellSouth will have no knowledge of the presence of DSL. In such a case, BellSouth has no basis to notify the carrier and the ability of the competitive carrier to provide DSL service may be affected.

Contact: <u>Technical questions</u> relating to this change should be directed to:	Gláucio T. Pessoa, P.E. 9101 SW 24 th Av Miami, Florida 33165 Phone: (305) 222-8237
---	---

All other questions or concerns regarding this change should be referred to your BellSouth account team representative, the Interexchange Carrier Service Center (ICSC) or the Local Interconnection Service Center (LISC). Payphone Service Providers should contact the following numbers with questions or concerns:

In the BellSouth region: 557-2647 (AL, KY, LA, MS, TN) or
780-2171 (FL, GA, NC, SC)
(If you are calling from a mandatory 10-digit calling area,
include your local area code.)

Outside BellSouth region: 1-800-786-7619
Fax: 1-205-321-2191

Attachment: 1

Notice of Network Change Under Rule 51.329(a)
Notification No. ND20040337
Issue Date: January 7, 2005
Issue Date 2: August 16, 2005

ADDRESS LIST

Below is a list of addresses that may be impacted by a conversion from copper-fed to fiber-fed carrier for wirecenter "miamflsh" sorted by hno and street.

HOUSE NUMBER	STREET	FLR	UNIT	BLDG
9990	NE 2ND AV			
9990	NE 2ND AV	1		
9990	NE 2ND AV	2		
10050	NE 2ND AV			

**Revision to Notice of Network Change – Miami Shores, Florida
Replacing Copper Facilities with Fiber and Digital Loop Carrier Systems
Carrier**

BellSouth Telecommunications, Inc.
675 West Peachtree Street NE
Atlanta, Georgia 30375

Attachment to the revised notification contains addresses affected by the removal of copper facilities.

Date Changes are to Occur: First Quarter 2006

Notice of Network Change:

Notice of Network Change ND20040336, originally posted on December 29, 2004, regarding Replacing Copper Facilities with Fiber and Digital Loop Carrier Systems in Miami Shores, FL.

Issue 2: Reason for Revision:

Due to the complexity of the work required and due to the current workload assigned to construction resources, the completion of this work has been rescheduled for the first quarter of 2006.

For further information please review the revised Notice of Network Change.

**Revised - Notice of Network Change – Miami Shores, Florida
Replacing Copper Facilities with Fiber and Digital Loop Carrier Systems**

Carrier

BellSouth Telecommunications, Inc.
675 West Peachtree Street NE
Atlanta, Georgia 30375

Attachment contains addresses affected by the removal of copper facilities.

Date Changes are to Occur: First Quarter of 2006

Location of Changes: THE AREA DELIMITED BY NE 97TH ST TO THE NORTH, NE 2ND AV TO THE EAST, NE 96TH ST TO THE SOUTH, AND NE 1ST AV ALLEY TO THE WEST.

Description of Change Planned: Copper Facilities will be replaced with Fiber Optic cable and Digital Loop Carrier systems.

Description of Reasonably Foreseeable Impact of the Planned Change: After this work is completed, metallic facilities from the Central Office to the affected area will no longer be available. Unbundled loops that are defined as compatible with Digital Loop Carrier (DLC), e.g., those defined to transport POTS-grade service, will be transferred to the new DLC system. Competitive carriers employing unbundled loops that are defined to require metallic facilities, e.g., Digital Subscriber Line (DSL) or line sharing circuits, will be notified individually. This notification is intended to allow the affected carrier to convert the circuit to one compatible with DLC.

It should be noted that if a competitive carrier obtains an unbundled loop that has been defined to transport POTS-grade service, but then utilizes the POTS-grade loop to provide DSL service, BellSouth will have no knowledge of the presence of DSL. In such a case, BellSouth has no basis to notify the carrier and the ability of the competitive carrier to provide DSL service may be affected.

Contact:	<u>Technical questions</u> relating to this change should be directed to:	Gláucio T. Pessoa, P.E. 9101 SW 24 th Av Miami, Florida 33165 Phone: (305) 222-8237
-----------------	---	---

All other questions or concerns regarding this change should be referred to your BellSouth account team representative, the Interexchange Carrier Service Center (ICSC) or the Local Interconnection Service Center (LISC). Payphone Service Providers should contact the following numbers with questions or concerns:

In the BellSouth region: 1-888-557-0667

Outside BellSouth region: 1-800-786-7619
Fax: 1-205-321-2191

Attachment: 1

Notice of Network Change Under Rule 51.329(a)
Notification No. ND20040336
Issue Date: December 29, 2004
Issue Date 2: August 18, 2005

ADDRESS LIST

Below is a list of addresses that may be impacted by a conversion from copper-fed to fiber-fed carrier for wirecenter "miamflsh" sorted by hno and street.

hno	st	unit	bldg
9600	ne 2nd av		
9608	ne 2nd av		
9612	ne 2nd av		
9612	ne 2nd av	c	
9620	ne 2nd av		
9620	ne 2nd av		200
9620	ne 2nd av		201
9620	ne 2nd av		202
9620	ne 2nd av		203
9620	ne 2nd av		205
9620	ne 2nd av		207
9620	ne 2nd av		209
9620	ne 2nd av		211
9623	ne 2nd av		
9628	ne 2nd av		
9628	ne 2nd av		102
9628	ne 2nd av	a	
9628	ne 2nd av	b	
9628	ne 2nd av	b-1	
9628	ne 2nd av	b-103	
9628	ne 2nd av	b-2	
9628	ne 2nd av	b1	
9628	ne 2nd av	c	
9628	ne 2nd av	d	
9628	ne 2nd av	e	
9629	ne 2nd av		
9630	ne 2nd av		
9636	ne 2nd av		
9636	ne 2nd av	c	
9640	ne 2nd av		
9640	ne 2nd av	computer	
9640	ne 2nd av	telco	
100	ne 2nd av & 98th st		
155	ne 96th st		
165	ne 96th st		
175	ne 96th st		
179	ne 96th st		

**Notice of Network Change – Richmond, Kentucky
Replacing Copper Facilities with Fiber and Digital Loop Carrier Systems**

Carrier

BellSouth Telecommunications, Inc.
675 West Peachtree Street NE
Atlanta, Georgia 30375

Attachment contains addresses affected by the removal of copper facilities.

Date Changes are to Occur: Second Quarter 2006

Location of Changes: Columbia, LA

Description of Change Planned: Copper Facilities will be replaced with Fiber Optic cable and Digital Loop Carrier systems.

Description of Reasonably Foreseeable Impact of the Planned Change: After this work is completed, metallic facilities from the Central Office to the affected area will no longer be available. Unbundled loops that are defined as compatible with Digital Loop Carrier (DLC), e.g., those defined to transport POTS-grade service, will be transferred to the new DLC system. Competitive carriers employing unbundled loops that are defined to require metallic facilities, e.g., Digital Subscriber Line (DSL) or line sharing circuits, will be notified individually. This notification is intended to allow the affected carrier to convert the circuit to one compatible with DLC.

It should be noted that if a competitive carrier obtains an unbundled loop that has been defined to transport POTS-grade service, but then utilizes the POTS-grade loop to provide DSL service, BellSouth will have no knowledge of the presence of DSL. In such a case, BellSouth has no basis to notify the carrier and the ability of the competitive carrier to provide DSL service may be affected.

Contact:	<u>Technical questions</u>	Ken Breard
	relating to this change	301 Catalpa St, 4 th Floor
	should be directed to:	Monroe, LA 71201
		318-388-8421

All other questions or concerns regarding this change should be referred to your BellSouth account team representative, the Interexchange Carrier Service Center (ICSC) or the Local Interconnection Service Center (LISC). Payphone Service Providers should contact the following numbers with questions or concerns:

In the BellSouth region: 1-888-557-0667

Outside BellSouth region: 1-800-786-7619
Fax: 1-205-321-2191

Attachment

ADDRESS LIST

Below is a list of addresses that may be impacted by a conversion from copper-fed to fiber-fed carrier for wirecenter "clmalama" sorted by hno and street.

hno bldg	st	unit
376	airport rd	
442	airport rd	
450	airport rd	
110	page rd	
138	page rd	
156	page rd	
174	page rd	
214	page rd	
334	page rd	
432	page rd	
573	page rd	
107	patton dr pvt dr	
109	patton dr pvt dr	
1004	rodeo rd	
747	rodeo rd	
750	rodeo rd	
766	rodeo rd	
776	rodeo rd	
788	rodeo rd	
800	rodeo rd	
812	rodeo rd	
818	rodeo rd	
826	rodeo rd	
862	rodeo rd	
944	rodeo rd	
954	rodeo rd	
980	rodeo rd	
999	rodeo rd	
5424	u s hwy 165	
6009	u s hwy 165	

6036	u s hwy 165	
6044	u s hwy 165	
6050	u s hwy 165	
6296	u s hwy 165	
6296	u s hwy 165	trailer
6365	u s hwy 165	2
6365	u s hwy 165	
2		

-----+-----+-----
+-----+
(37 rows)

hno	st	unit
bldg		
-----+-----+-----		
308	agnew rd	
108	alpha ln pvt dr	
102	breton ln	
111	breton ln	
119	breton ln	
120	breton ln	
122	breton ln	
149	breton ln	
157	breton ln	
276	breton ln	
276	columbia nursery rd	
276	columbia nursery rd	
nursery	columbia nursery rd	
338	columbia nursery rd	
351	columbia nursery rd	
356	columbia nursery rd	
436	columbia nursery rd	
131	fox run ln pvt dr	
ahn-4425	hwy 4	
120	lock office rd	
208	lock office rd	
284	lock office rd	
302	lock office rd	
580	lock office rd	
580	lock office rd	trailer

599	lock office rd	yacht
155	martin place rd	
203	martin place rd	
226	oak ln pvt dr	
3815	u s hwy 165	
3869	u s hwy 165	
3913	u s hwy 165	
3981	u s hwy 165	
4193	u s hwy 165	
4223	u s hwy 165	
4228	u s hwy 165	
4349	u s hwy 165	
4400	u s hwy 165	
4403	u s hwy 165	
4415	u s hwy 165	
4417	u s hwy 165	
4445	u s hwy 165	
4447	u s hwy 165	
4480	u s hwy 165	
4488	u s hwy 165	
4566	u s hwy 165	
4583	u s hwy 165	
4603	u s hwy 165	
4617	u s hwy 165	
4645	u s hwy 165	
4731	u s hwy 165	
4784	u s hwy 165	
158	volman lake rd	
266	volman lake rd	
753	volman lake rd	
765	volman lake rd	

(55 rows)

hno	st	unit
bldg		
131 hwy 847		

279	brown rd	
570	brown rd	
595	brown rd	
208	coon rd	
224	cooper rd	
111	cumpton cir pvt dr	
133	cumpton cir pvt dr	6
168	cumpton cir pvt dr	10
168	cumpton cir pvt dr	11
168	cumpton cir pvt dr	12
168	cumpton cir pvt dr	13
168	cumpton cir pvt dr	15
168	cumpton cir pvt dr	17
168	cumpton cir pvt dr	18
168	cumpton cir pvt dr	19
168	cumpton cir pvt dr	2
168	cumpton cir pvt dr	24
168	cumpton cir pvt dr	26
168	cumpton cir pvt dr	3
168	cumpton cir pvt dr	5
168	cumpton cir pvt dr	9
172	eglin st	
186	esperance ln	10
266	esperance ln	
398	esperance ln	
763	esperance ln	
365	hart rd	
163	hartford rd	
259	hartford rd	
119	horton rd	
136	horton rd	
277	horton rd	
315	horton rd	
600	horton rd	
643	horton rd	house

643	horton rd	trailer
100	hwy 847	
1037	hwy 847	
1210	hwy 847	
1259	hwy 847	
1379	hwy 847	
1379	hwy 847	trlr
1381	hwy 847	
1386	hwy 847	
1586	hwy 847	
208	hwy 847	
243	hwy 847	
477	hwy 847	
550	hwy 847	
576	hwy 847	
586	hwy 847	
706	hwy 847	
709	hwy 847	
739	hwy 847	
232	k n o e tower rd	
113	reynolds rd	
203	reynolds rd	
104	riverton camp rd	
105	riverton camp rd	105
118	riverton camp rd	59
351	riverton camp rd	
439	riverton camp rd	10
503	riverton camp rd	105
531	riverton camp rd	
531	riverton camp rd	1
531	riverton camp rd	10
531	riverton camp rd	102
531	riverton camp rd	103
531	riverton camp rd	104
531	riverton camp rd	105
531	riverton camp rd	106

531		riverton camp rd	107
531		riverton camp rd	108
531		riverton camp rd	109
531		riverton camp rd	110
531		riverton camp rd	111
531		riverton camp rd	112
531		riverton camp rd	113
531		riverton camp rd	13
531		riverton camp rd	15
531		riverton camp rd	17
531		riverton camp rd	18
531		riverton camp rd	2
531		riverton camp rd	2-a
531		riverton camp rd	20
531		riverton camp rd	22
531		riverton camp rd	23
531		riverton camp rd	25
531		riverton camp rd	29
531		riverton camp rd	3
531		riverton camp rd	30
531		riverton camp rd	31
531		riverton camp rd	32
531		riverton camp rd	34
531		riverton camp rd	35
531		riverton camp rd	36
531		riverton camp rd	36-a
531		riverton camp rd	36-aa
531		riverton camp rd	36-b
531		riverton camp rd	36-c
531		riverton camp rd	37
531		riverton camp rd	38
531		riverton camp rd	4
531		riverton camp rd	42
531		riverton camp rd	43
531		riverton camp rd	44

531		riverton camp rd	45
531		riverton camp rd	46
531		riverton camp rd	49
531		riverton camp rd	5
531		riverton camp rd	50
531		riverton camp rd	51
531		riverton camp rd	52
531		riverton camp rd	53
531		riverton camp rd	54
531		riverton camp rd	55
531		riverton camp rd	56
531		riverton camp rd	57
531		riverton camp rd	58
531		riverton camp rd	59
531		riverton camp rd	6
531		riverton camp rd	60
531		riverton camp rd	61
531		riverton camp rd	62
531		riverton camp rd	63
531		riverton camp rd	65
531		riverton camp rd	66
531		riverton camp rd	67
531		riverton camp rd	69
531		riverton camp rd	7
531		riverton camp rd	70
531		riverton camp rd	71
531		riverton camp rd	72
531		riverton camp rd	73
531		riverton camp rd	74
531		riverton camp rd	76
531		riverton camp rd	78
531		riverton camp rd	8
531		riverton camp rd	89
531		riverton camp rd	9
913		riverton camp rd	
917		riverton camp rd	

[illegible]

198		anderson ln	
107		davis rd	
123		davis rd	
173		davis rd	
117		esaw rd	
139		esaw rd	
180		johnson rd	
223		johnson rd	
278		johnson rd	
347		johnson rd	
383		johnson rd	
393		johnson rd	
428		johnson rd	
467		johnson rd	
529		johnson rd	
543		johnson rd	
591		johnson rd	
621		johnson rd	
633		johnson rd	
641		johnson rd	
691		johnson rd	
692		johnson rd	
763		johnson rd	
109		martha ln pvt dr	
163		martha ln pvt dr	
165		powell rd	13
310		powell rd	
320		powell rd	
358		powell rd	
1063		s blankston rd	
1233		s blankston rd	
126		s blankston rd	
1273		s blankston rd	
1329		s blankston rd	
1439		s blankston rd	

156	s blankston rd	
1577	s blankston rd	
160	s blankston rd	
1634	s blankston rd	
1654	s blankston rd	
1702	s blankston rd	
1773	s blankston rd	
238	s blankston rd	
256	s blankston rd	
286	s blankston rd	
356	s blankston rd	
395	s blankston rd	
403	s blankston rd	
411	s blankston rd	
421	s blankston rd	
423	s blankston rd	
448	s blankston rd	
469	s blankston rd	
507	s blankston rd	
555	s blankston rd	
1040	s sampson rd	
1262	s sampson rd	
1266	s sampson rd	
1416	s sampson rd	
1436	s sampson rd	
1440	s sampson rd	
1464	s sampson rd	
1524	s sampson rd	
1526	s sampson rd	
1563	s sampson rd	
1565	s sampson rd	
1575	s sampson rd	
1597	s sampson rd	
1614	s sampson rd	
1658	s sampson rd	
1805	s sampson rd	

814		sampson rd	
938		sampson rd	
970		sampson rd	
114		thornton ln	
124		thornton ln	
1118		u s hwy 165	
1384		u s hwy 165	
1408		u s hwy 165	
1882		u s hwy 165	
2006		u s hwy 165	
ahn-7085		u s hwy 165	
+-----+			
{84 rows}			